

6160RF-2 PICTURES OF THE UNIT UNDER TEST

SENSE=HORZ UUT=HORZ



SENSE=HORZ UUT=VERT



SENSE=HORZ UUT=OBLQ



SENSE=VERT UUT=VERT



SENSE=VERT UUT=HORZ



SENSE=VERT UUT=OBLQ



PICTURE OF THE OATS AT
2 CORPORATE CENTER DRIVE
MELVILLE, NY 11747



TEST SETUP PICTURES (CONT.)

