




13.7 EUT Photo – Cover off Top View**13.8 EUT Photo – Cover off Bottom View**

13.9 EUT Photo – Microphone removed View**13.10 EUT - Antenna**


13.11 HHA Audio Logic Top View




13.12 HHA Audio Logic Bottom View



13.13 HHA C1 Radio Top View



13.14 HHA C1 Radio Bottom View



--- END OF REPORT ---