

# Photos

---

## Emission tests to FCC and IC requirements of HA03

**Performed for Intermatic Inc.**

Page 1 of 3

This exhibit is an extract of

DELTA Test Report E501839-1  
DANAK-197369  
5 March 2004

containing only the photos of the test set-ups

**DELTA**  
Danish Electronics,  
Light & Acoustics

Venlighedsvej 4  
2970 Hørsholm  
Denmark

Tel. (+45) 72 19 40 00  
Fax (+45) 72 19 40 01  
[www.delta.dk](http://www.delta.dk)





Photo 1      Set-up for conducted emission measurements.  
The LISN is bonded to the vertical ground plane (wall) of the screened room.




Photo 2      Set-up for conducted emission measurements.  
The LISN is bonded to the vertical ground plane (wall) of the screened room.



Photo 3      Set-up for measurements 30 – 1000 MHz. Date is 2004-02-12. Camera time is faulty.



Photo 4      Measurement set-up > 1 GHz.