

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL81208

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL82218

Radiated Emission – Base Unit



Front View



Rear View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Handset



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL81208

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL81208

Conducted Emission



Left Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL82218

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs - Model: SL82218

Conducted Emission



Left Side View