



## PHOTOS - TEST SETUP


Company: Itron

Product Name: ERG-7600-008


Report No.: ITRO67 – Test Setup Photos

## 1. Test Setup Photographs

### 1.1.1. Test Setup



Digital Emissions ERG-7600-008 30MHz-1GHz Back




Digital Emissions ERG-7600-008 30MHz-1GHz Front



Digital Emissions ERG-7600-008 1-18GHz Front




ERG-7600-008 30MHz-1GHz Back



ERG-7600-008 30MHz-1GHz Front




Spurious Emissions ERG-7600-008 1-18GHz Front




Spurious Emissions ERG-7600-008 1-18GHz Back

### 1.1.2. Test Setup - RF#2 - Conducted



RF Conducted Test Setup 1



RF Conducted Test Setup 2



**Title:** ITRO67 ERG-7600-008 Test Setup Photos  
**To:**  
**Serial #:**

ERG-7600-008 deemed by Itron to be the worst case and covers the following models also. Please see Declaration of Similarity in reports:

ERG-7600-007



575 Boulder Court  
Pleasanton, California 94566, USA  
Tel: +1 (925) 462 0304  
Fax: +1 (925) 462 0306  
[www.micomlabs.com](http://www.micomlabs.com)