




Compliance Testing, LLC
Testing since 1963

Annex C


Conducted Spurious Emissions



Downlink High side_high ch_AWGN




Downlink High side_high ch_GSM






Downlink High side_low ch_AWGN




Downlink High side_low ch_GSM






Downlink Low side_high ch_AWGN




Downlink Low side_high ch_GSM






Downlink Low side_low ch_AWGN




Downlink Low side_low ch_GSM






Uplink High side_high ch_AWGN




Uplink High side_high ch_GSM






Uplink High side_low ch_AWGN




Uplink High side_low ch_GSM






Uplink Low side_high ch_AWGN




Uplink Low side_high ch_GSM





Uplink Low side_low ch_AWGN



Uplink Low side_low ch_GSM

