

Photo # 3      Unit Partially Disassembled ( SCORPIUS 980 )



Photo # 4      Unit Partially Disassembled    ( SCORPIUS 980 )



Photo # 5      Unit Partially Disassembled    ( SCORPIUS 980 )

98E1255




Photo # 6      Unit Partially Disassembled    ( SCORPIUS 980 )

98E1255




Photo # 7      Unit Partially Disassembled    ( SCORPIUS 980 )

98E1255





Photo # 10      Unit Partially Disassembled    ( SCORPIUS 980N plus )



Photo # 11

Unit Partially Disassembled ( SCORPIUS 980N plus )



98E1255

Photo # 12      Unit Partially Disassembled    ( SCORPIUS 980N plus )

98E1255




Photo # 13      Unit Partially Disassembled    ( SCORPIUS 980N plus )

98E1255




Photo # 14      Unit Partially Disassembled    ( SCORPIUS 980N plus )

98E1255

