

**Annex B.iii. Photograph: Test Setup Photo**

 A photograph showing a laptop on a wooden table in a test chamber. The table is positioned in front of a metal frame. Various test equipment and cables are visible on the table and the floor.	 A photograph showing a laptop on a wooden table in a test chamber. The laptop is viewed from the side, showing its keyboard and the back of the screen. Cables are visible on the table.
Conducted Emissions Test Setup – Front View	Conducted Emissions Test Setup – Side View
 A photograph showing a laptop on a white marble table in a test chamber. The table is positioned in front of a metal frame. A red circle highlights a small device on the table. Cables are visible on the table.	 A photograph showing a laptop on a white marble table in a test chamber. The table is positioned in front of a metal frame. A red circle highlights a small device on the table. Cables are visible on the table.
Radiated Spurious Emissions Test Setup Below 1GHz	Radiated Spurious Emissions Test Setup Above 1GHz