


Test Setup Photos for RM-88 SAR Compliance Test Report

Test report no.:	WR897.001_V2	Date of report:	2006-03-28
Template version:	5	Number of pages:	4
Testing laboratory:	TCC, Dallas Nokia, Inc. 6021 Connection Drive Irving, TX 75039, USA Tel. +1 972 894 5000 Fax +1 972 894 4988	Client:	TCC, Dallas Nokia, Inc. 6021 Connection Drive Irving, TX 75039, USA Tel. +1 972 894 5000 Fax +1 972 894 4988
Responsible test engineer:	Anu Balijepalli	Product contact person:	Jarmo Alm
Measurements made by:	Anu Balijepalli; Bob Alexander		
Tested device:	RM-88		
FCC ID:	GMLRM-88A	IC:	661N-RM88A
Supplement reports:	-		

Documentation: The documentation of the testing performed on the tested devices is archived for 15 years at TCC Dallas.

Date and signatures: 2006-03-28

For the contents:



Anu Balijepalli
Test Engineer



Nerina Walton
Lab Manager

CONTENTS

1. SUMMARY OF SAR TEST REPORT	3
1.1 TEST DETAILS	3
1.2 PICTURE OF THE DEVICE	3
1.3 TEST POSITIONS	3
1.3.1 <i>Against Phantom head</i>	3
1.3.2 <i>Body Worn Configuration</i>	3

1. SUMMARY OF SAR TEST REPORT

1.1 Test Details

Period of test	2005-12-09 to 2005-12-29
SN, HW and SW numbers of tested device	001004/00/192397/9, B4.0, V5.4002
Batteries used in testing	BP-5L
Headsets used in testing	HS-40
Other accessories used in testing	Mini SD Card 512 MB
State of sample	Prototype unit
Notes	-

1.2 Picture of the Device



1.3 Test Positions

1.3.1 Against Phantom head




Photo of the device in “cheek” position



Photo of the device in “tilt” position

1.3.2 Body Worn Configuration



Photo of the device positioned for Body SAR measurement.
The spacer was removed for the tests.