


APPENDIX 3: Photographs of test setup


Radiated Spurious Emission



Below 1 GHz



Above 1 GHz



Worst Case Position

Antenna
X-axis




Y-axis




Z-axis



Module
X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report