
C SAR TEST REPORT Report No. :FA1N0506

## Appendix D. SAR Test Setup Photos

## Head Exposure Condition





Right Cheek at 0mm

Right Tilted at 0mm





Left Cheek at 0mm

Left Tilted at 0mm

TEL: 886-3-327-3456 Page: D1 of D3
FAX: 886-3-328-4978 Issued Date: Jan. 05, 2022

Template version: 200414

## **Body-worn Exposure Condition**





Front at 15mm









Back with Holster 2 at 0mm

TEL: 886-3-327-3456 Page: D2 of D3
FAX: 886-3-328-4978 Issued Date: Jan. 05, 2022

Template version: 200414



## **Extremity Exposure Condition**





Front at 0mm










Right side at 0mm



Top side at 0mm

TEL: 886-3-327-3456 Page: D3 of D3
FAX: 886-3-328-4978 Issued Date: Jan. 05, 2022

Template version: 200414