

EMC TEST SETUP PHOTOS



EMC Report #23575 AC Line - Part 15




EMC Report #23575 AC Line - Part 15



EMC Report #23575 Part 15, PC Peripheral front view



EMC Report #23575 Part 15, PC Peripheral rear view




EMC Report #23574Antenna - Substitution



EMC Report #23575 Tx Radiated



EMC Report #23575 Tx Radiated



EMC Report #23575 Tx Radiated