


PHOTOGRAPHS  
F40PH- DIESEL LOCOMOTIVE





**Retlif Testing Laboratories**

Test Report Number R-7864-2

PHOTOGRAPHS



F40PH- DIESEL LOCOMOTIVE 27 MHz ANTENNA /4.5 MHz TX LOCATION



Retlif Testing Laboratories

Test Report Number R-7864-2

PHOTOGRAPHS  
ARROW III ELECTRIC LOCOMOTIVE





Retlif Testing Laboratories

Test Report Number R-7864-2

PHOTOGRAPHS

ARROW III ELECTRIC LOCOMOTIVE 27 MHz ANTENNA /4.5 MHz TX LOCATION



**Retlif Testing Laboratories**

Test Report Number R-7864-2

PHOTOGRAPHS  
COMET-CAB CAR ELECTRIC LOCOMOTIVE



**Retlif Testing Laboratories**

Test Report Number R-7864-2

PHOTOGRAPHS

COMET-CAB CAR LOCOMOTIVE 27 MHz ANTENNA /4.5 MHz TX LOCATION



**Retlif Testing Laboratories**

Test Report Number R-7864-2