


INTERNAL PHOTOGRAPHS

This document contains 7 photographs


Photograph No.1
RK200DT0000A ceiling detector internal view




Photograph No.2
RK200DT0000A internal view



Photograph No.3
RK200DT0000A detector, component side of the main PCB



Photograph No.4
Component side of the main PCB with the Tx board removed



Photograph No.5
RK200DT0000A detector, print side of the main PCB




Photograph No.6
Print side of the RF PCB and antenna view



Photograph No.7
Component side of the RF PCB



Photograph No.8
Shielding compartments of the RF PCB



Photograph No.9
RF PCB component side

