


RADIATED EMISSIONS TEST SETUP

The following page has photographs of the test setup of the EUT. In the lower photograph, one of the test antennas was moved from the test distance and was positioned so that it would appear in the photograph. Testing was performed at correct antenna distance.



Retlif Testing Laboratories

Test Report No. R-3293N
FCC ID: KF5ORTOVOXM1

RADIATED EMISSIONS TEST SETUP PHOTOGRAPHS



Retlif Testing Laboratories

Test Report No. R-3293N
FCC ID: KF5ORTOVOXM1