

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1





Photo 2

Worst Case Position


Antenna (Horizontal: Y-axis / Vertical: Y-axis)

Module (Horizontal: Y-axis / Vertical: Y-axis)


Antenna
X-axis




Y-axis



Z-axis



Module
X-axis




Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo

End of Report