



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

APPENDIX A: TEST CONFIGURATION PHOTOS



PHOTOGRAPH 1: RADIATED MEASUREMENT FRONT VIEW (ITRONIX IX250)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 2: RADIATED MEASUREMENT REAR VIEW (ITRONIX IX250)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 3: RADIATED MEASUREMENT FRONT VIEW WITH CRADLE (ITRONIX IX250)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 4: RADIATED MEASUREMENT REAR VIEW WITH CRADLE (ITRONIX IX250)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 5: RADIATED MEASUREMENT FRONT VIEW (ITRONIX IX550)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 6: RADIATED MEASUREMENT BACK VIEW (ITRONIX IX550)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 7: RADIATED MEASUREMENT FRONT VIEW WITH CRADLE (ITRONIX IX550)



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 8: RADIATED MEASUREMENT BACK VIEW WITH CRADLE (ITRONIX IX550)