

17 TEST SETUP PHOTOGRAPHS


Picture 1: Radiated emission test setup <3 GHz




Picture 2: Radiated emission test setup 3 GHz – 18 GHz




Picture 4: Conducted emissions to AC-mains test setup




Picture 4: Photo of the EUT on board



Picture 5: Photo of the EUT top



Picture 6: Photo of the EUT bottom



Test results are valid for the tested unit only.

The report may be copied only in its entirety

DVT ConnectCore Wi-9P 9215- WLAN part
08KFE010163-C-01 / 2008-15-17