


Appendix B. Test Photos

1. Photographs of Conducted Emissions Test Configuration

FRONT VIEW




REAR VIEW




2. Photographs of Radiated Emissions Test Configuration

9kHz ~30MHz

FRONT VIEW



REAR VIEW




30MHz~1GHz

FRONT VIEW



REAR VIEW




SIDE VIEW





Above 1GHz

FRONT VIEW



REAR VIEW





The image shows the rear of a Dell server chassis. On the left, there are several cooling fans with a circular grille pattern. Below the fans, there are various ports and connectors, including a large black power connector with a red cable, and several smaller ports (red, green, blue). A label with technical specifications is visible on the right side of the chassis. The server is resting on a yellow surface.