


Appendix L: Test Photographs



Photograph 1: Unintentional Radiated Emissions Testing – Front View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: Vocollect, Inc.
Model #: HBT1000-01
Standards: FCC 15.247 & RSS-210
ID's:MQO-HBT1000-01/2570A-HBT100001
Report #: 2012186



Photograph 2: Unintentional Radiated Emissions Testing – Back View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Vocollect, Inc.
Model #: HBT1000-01
Standards: FCC 15.247 & RSS-210
ID's:MQO-HBT1000-01/2570A-HBT100001
Report #: 2012186



Photograph 3: Conducted Emissions Testing – Front View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Vocollect, Inc.
Model #: HBT1000-01
Standards: FCC 15.247 & RSS-210
ID's:MQO-HBT1000-01/2570A-HBT100001
Report #: 2012186



Photograph 4: Conducted Emissions Testing – Back View