


Appendix J: Test Photographs



Photograph 1: Unintentional Radiated Emissions Testing – Front View



Photograph 2: Unintentional Radiated Emissions Testing – Back View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Vocollect, Inc.
Model #: TAP801-01
Standards: FCC 15.247 & RSS-210
FCC ID: MQO-TAP801-01
Report #: 2011184-1



Photograph 3: Conducted Emissions Testing – Front View

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Vocollect, Inc.
Model #: TAP801-01
Standards: FCC 15.247 & RSS-210
FCC ID: MQO-TAP801-01
Report #: 2011184-1



Photograph 4: Conducted Emissions Testing – Back View