


PHOTOGRAPHS OF TEST SETUP


Test mode No: GWP-SLCR2-BT




Radiated spurious emission Test Setup-1 left ears(Below 30MHz)




Radiated spurious emission Test Setup-2 right ears(Below 30MHz)




Radiated spurious emission Test Setup-1 left ears(Below 1GHz)



Radiated spurious emission Test Setup-2 right ears(Below 1GHz)



Radiated spurious emission Test Setup-1 left ears(Above 1GHz)



Radiated spurious emission Test Setup-2 right ears(Above 1GHz)



Radiated spurious emission Test Setup
There are absorbing materials under the ground.



Conducted Emissions

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32M00142401 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.