


Prüfbericht - Nr.: 16004795 001
Test Report No.:

Seite 15 von 17
Page 15 of 17

6 Photographs of the Test Set-Up


Photograph 1: Set-up for Conducted Emission on AC Mains



Prüfbericht - Nr.: 16004795 001
Test Report No.:

Seite 16 von 17
Page 16 of 17

Photograph 2: Set-up for Radiation Measurement Below 1GHz



Photograph 3: Set-up for Radiation Measurement Above 1GHz

