

6. Photos of testing

C. Open site test front view

D. Open site test back view



6. Photos of testing
E. Conducted test front view
F. Conducted test back view



6. Photos of testing

G. Computer front view



H. Computer back view



6. Photos of testing

I. Computer left side view


J. Computer right side view



6. Photos of testing

K. Computer inside whole view


L. Computer case inside view of cover



6. Photos of testing

M. Computer chassis inside view


N. Computer front panel inside view



6. Photos of testing

O. Power supply whole view



P. Computer supply inside view





6. Photos of testing

Q. power supply component side

R. power supply solder side



6. Photos of testing
S. AGP VGA Card component side
T. AGP VGA Card solder side



6. Photos of testing

U. mother board with Pentium II-300 CPU view

