



---

### **APPENDIX 3: Photographs of Test Setup**

#### **Radiated Spurious Emission**



**Photo 1**



**Photo 2**

### Worst Case Position

| Test Range  | Horizontal                                                     | Vertical                                                       |
|-------------|----------------------------------------------------------------|----------------------------------------------------------------|
| Below 1 GHz | Antenna 0: X-axis<br>Antenna 1: X-axis<br>WLAN Module : X-axis | Antenna 0: X-axis<br>Antenna 1: X-axis<br>WLAN Module : X-axis |
| Above 1 GHz | Antenna 0: X-axis<br>Antenna 1: X-axis<br>WLAN Module : X-axis | Antenna 0: Y-axis<br>Antenna 1: Y-axis<br>WLAN Module : X-axis |


**Antenna 0**  
**X-axis**




**Antenna 1**  
**X-axis**



**Y-axis**



**Y-axis**




---


**Worst Case Position**

**WLAN Module**


**X-axis**



**Y-axis**



**Z-axis**



**End of Report**