


### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

### Radiated Spurious Emission



**Photo 1**




**Photo 2**

**Worst Case Position**

(Below 1GHz Horizontal: Y-axis/ Vertical:Y-axis)  
(Above 1GHz Horizontal: Z-axis/ Vertical:Y-axis)

**X-axis**



**Y-axis**



**Z-axis**



### Antenna Terminal Conducted Tests



**Photo 1**

**End of Report**