

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission




Photo 1




Photo 2


Worst Case Position

Below 1GHz (Horizontal: Y-axis/ Vertical:Y-axis)

Above 1GHz (Horizontal: Z-axis/ Vertical:Y-axis)

2nd Harmonics (Horizontal: X-axis/ Vertical:Z-axis)

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



End of Report