Appendix 1





 Prüfbericht - Nr.:
 14011032 001
 Seite 1 von 1

 Test Report No.
 Page 1 of 1

•

RBW 3 kHz Marker 1 [T1] -28.13 dBm VBW 10 kHz 49.860200000 MHz Ref -10 dBm *Att 0 dB SWT 15 ms Delta 2 [T1] -36.54 dB -10 -50 200000000 kHz Delta B [T1] 1 PK -36 32 dB MAXH . 800000000 кнг

10 kHz/

Date: 5.JAN.2006 16:33:39

Start 49.81 MHz

LP

Stop 49.91 MHz

93045