




Report No.: FR711911-01

## Appendix B. Test Photos

## 1. Photographs of Conducted Emissions Test Configuration

**FRONT VIEW**




**REAR VIEW**




## 2. Photographs of Radiated Emissions Test Configuration

**9kHz ~1GHz**

**FRONT VIEW**



**REAR VIEW**




**FRONT VIEW**



**REAR VIEW**



**SIDE VIEW**



**Above 1GHz**

**FRONT VIEW**



**REAR VIEW**

