



APPENDIX A.
PHOTOS OF EUT APPEARANCE
< EUT FRONT VIEW >



< EUT REAR VIEW >





PEP Testing Laboratory

REPORT NO. : 980660

RADIATED TEST CONFIGURATION PHOTO.

< FRONT VIEW >



< REAR VIEW >





PEP Testing Laboratory

REPORT NO. : 980660

CONDUCTED TEST CONFIGURATION PHOTO.

< FRONT VIEW >

