

ITS Intertek Testing Services

ETL Testing Laboratories


Report No.: 99032801
Made! Charging

Tested By: Hong, Report No.: 99032801

Scan Settings: (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamplifier | OpRge |
| 450k | 30M | 5k | 10k | PK | 100ms | AUTO | LN OFF | 60dB |

| Final Measurement: | Transducer No. | Start | Stop | Name |
|--------------------|----------------|-------|------|-------|
| K QF | 3 | 9k | 30M | EI078 |
| Meas Time: | 1 s | | | |
| Subranges: | 16 | | | |
| Acc Margin: | 20dB | | | |



FG0156

NHz

Ctrl. No.: N/A

ITS Intertek Testing Services

ETL Testing Laboratories

Report No.: 99032801
Mode: Charging

Tested By: Hong, Report No.: 99032801

Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: N/A


Report No.: 99032801
Made: Standby

Tested By: Hong, Report No.: 99032801
 Scan Settings (1 Range)

| Frequencies | | | | Receiver Settings | | | |
|-------------|------|------|-------|-------------------|--------|-------|---------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Presamp |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LH OFF |

| Final Measurement: | Transducer No. | Start | Stop | Name |
|--------------------|----------------|-------|------|-------|
| 3 CP | 2 | 9k | 30M | EI076 |

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB



Ctrl. No.: N/A

Report No.: 99032801
Mode: Standby

Tested By: Hong, Report No.: 99032801

Scan Settings (1 Range)

| ----- Frequencies ----- | | | ----- Receiver Settings ----- | | | | | |
|-------------------------|------|------|-------------------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: *N/A*

Report No.: 99032801
 Mode: Transmission


Tested By: Hong, Report No.: 99032801

Scan Settings (1 Range)

| Frequencies | | | Receiver Settings | | | | | |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | K-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | IN OFF | 50dB |

| Final Measurement: N OP | Transducer No. | Start | Stop | Name |
|-------------------------|----------------|-------|------|-------|
| | 3 | 9k | 30M | EI078 |

Meas Time: 1 s
 Subrange: 16
 Acc Margin: 20dB



Ctrl. No.: N/A

ITS Intertek Testing Services

ETL Testing Laboratories

Report No.: 99032801
Mode: Transmission

Tested By: Hong, Report No.: 99032801

Scan Settings (1 Range)

| ----- Frequencies ----- | | | ----- Receiver Settings ----- | | | | | |
|-------------------------|------|------|-------------------------------|----------|--------|-------|--------|-------|
| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN OFF | 60dB |

Final Measurement Results:

no Results

Ctrl. No.: N/A