DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



Appendix C: Photographs

Report No: 4552ERM.019 11-20-2024






Figure C1. Front View of DUT




Figure C2. Rear View of DUT






Figure C3. Side View of DUT




Figure C4. Front View of Conducted and Radiated samples with Accessories






Figure C5. Low Range Radiated Emission test setup




Figure C6. High Range Radiated Emission test setup 1-18GHz




Figure C7. High Range Radiated Emission test setup 18-26GHz