



Ambient emissions scan  
EUT was removed from the chamber  
Noise spike are related to EMI receiver and Ethernet cable passing through the waveguide.



Layout of testing when cable lengths are critical for the measurement.  
Example here approximates the test position when testing at a 0.5 meter distance.

