


Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCIX-1000	194

Figure 5. General Configuration (Rear View)



Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCTX-1000	197


Figure 8. Test Configuration, Occupied Bandwidth



EUTs

Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCTX-1000	198

Figure 9. Test Configuration, Spurious Emissions



*EUTs located
inside enclosure*

Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCTX-1000	199


Figure 10. Test Configuration, Frequency Stability

EUTs



Electromagnetic Engineering Services, Inc.			11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax		
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCTX-1000	196

Figure 7. Test Configuration, Radiated Emissions



Electromagnetic Engineering Services, Inc.		11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name	Document #	FCC ID#	Page #
A	4/13/98	Cubic Communications CTX-1000 Part 87 Type Acceptance Report	98-046	NVSCTX-1000	195

Figure 6. Test Configuration, Conducted Emissions

