



Report # 86076-1
Photo # 8 Page # 11h
Internal View - Video PCB Top




Report # 86076-1
Photo # 9 Page # 111
Internal View – Video PCB Rear



Report # 86076-1
Photo # 10 Page # 11j
Internal View – Transmitter PCB Top
With shield removed




Report # 86076-1
Photo # 11 Page # 11k
Internal View – Transmitter PCB with
Shield



Report # 86076-1
Photo # 12 Page # 111
Internal View - Transmitter PCB Rear


http://www.technoimaging.com



Report # 86076-
Photo 13 Page # 1m
Internal View -Front Cover with
Antenna



Report # 86076-1
Photo 14 Page # 11n
Internal View – Tower unit with covers
Removed bottom left view



Report # 86076-1
Photo 15 Page # 11c
Internal View – Tower unit with bottom
and rear panels removed

