




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


APPENDIX G: TEST CONFIGURATION PHOTOGRAPHS



PHOTOGRAPH 2: RADIATED REAR VIEW




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 3: RADIATED FRONT VIEW



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 4: RADIATED/DIGITAL WITH DATA TRANSFER CABLE BACK SIDE




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 5: RADIATED/DIGITAL WITH DATA TRANSFER CABLE FRONT SIDE




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 6: DATA TRANSFER CABLE CONDUCTED LINE EMISSIONS FRONT SIDE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Data

PHOTOGRAPH 7: TRANSFER CABLE CONDUCTED LINE EMISSIONS BACK SIDE



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 8: CONDUCTED FRONT VIEW



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 9: CONDUCTED BACK VIEW