




Test Setup Photos


Report No.: 0807FR14

FCC ID: OGSMPR1712

Conducted Emissions



Front View of the Test Configuration



Rear View of the Test Configuration



Radiated Emissions

Loop antenna positioned at 0 degrees



Front View of the Test Configuration



Rear View of the Test Configuration



Loop antenna positioned at 90 degrees



Front View of the Test Configuration




Rear View of the Test Configuration



Below 1GHz



Front View of the Test Configuration



Rear View of the Test Configuration