



6. Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emissions




Photograph 2: Set-up for Radiated Emissions



Prüfbericht - Nr.: 17005738 001
Test Report No.

Seite 53 von 54
Page 53 of 54

Photograph 3: Set-up for Transmitter test



Photograph 4: Set-up for Spurious Emissions

