



Report No.: 9911377

Tested By: Hong, Report No.: 9911377


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 15
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl No.:



Intertek Testing Services

ETL SEMKO

Report No.: 9911377

Tested By:Hong, Report No.:9911377

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
-------	------	------	-------	----------	--------	-------	--------	-------

450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB
------	-----	----	-----	----	------	------	----	----------

Final Measurement Results:

no Results

Ctrl No.: