


Rhein Tech Laboratories  
360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

Client: M/A COM, Inc.  
Model: P7100<sup>P</sup> 800 MHz Portable Radio  
Standards: FCC Part 90/IC RSS-119  
Report Number: 2004058  
Date: June 21, 2004

**APPENDIX L: INTERNAL PHOTOGRAPHS**



**PHOTOGRAPH 3: VIEW OF REAR CASTING**

Rhein Tech Laboratories  
360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


Client: M/A COM, Inc.  
Model: P7100<sup>P</sup> 800 MHz Portable Radio  
Standards: FCC Part 90/IC RSS-119  
Report Number: 2004058  
Date: June 21, 2004



PHOTOGRAPH 4: VIEW OF INSIDE OF FRONT COVER

Rhein Tech Laboratories  
360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


Client: M/A COM, Inc.  
Model: P7100<sup>P</sup> 800 MHz Portable Radio  
Standards: FCC Part 90/IC RSS-119  
Report Number: 2004058  
Date: June 21, 2004



PHOTOGRAPH 5: **VIEW OF TOP OF INTERFACE BOARD AND RF SHIELD**

Rhein Tech Laboratories  
360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

Client: M/A COM, Inc.  
Model: P7100<sup>P</sup> 800 MHz Portable Radio  
Standards: FCC Part 90/IC RSS-119  
Report Number: 2004058  
Date: June 21, 2004



PHOTOGRAPH 6: **VIEW OF TOP OF INTERFACE BOARD**