


Rhein Tech Laboratories
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: M/A COM, Inc.
Model: P7100^P 800 MHz Portable Radio
Standards: FCC Part 90/IC RSS-119
Report Number: 2004058
Date: June 21, 2004



PHOTOGRAPH 7: VIEW OF BOTTOM OF INTERFACE BOARD

Rhein Tech Laboratories
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: M/A COM, Inc.
Model: P7100^P 800 MHz Portable Radio
Standards: FCC Part 90/IC RSS-119
Report Number: 2004058
Date: June 21, 2004



PHOTOGRAPH 8: VIEW OF TOP OF RF SHIELD WITH INTERFACE BOARD REMOVED

Rhein Tech Laboratories
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: M/A COM, Inc.
Model: P7100^P 800 MHz Portable Radio
Standards: FCC Part 90/IC RSS-119
Report Number: 2004058
Date: June 21, 2004




PHOTOGRAPH 9: VIEW OF TOP OF MAIN BOARD WITH RF SHIELD REMOVED

Rhein Tech Laboratories
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: M/A COM, Inc.
Model: P7100^P 800 MHz Portable Radio
Standards: FCC Part 90/IC RSS-119
Report Number: 2004058
Date: June 21, 2004



PHOTOGRAPH 10: **VIEW OF BOTTOM OF MAIN BOARD**



PHOTOGRAPH 11: VIEW OF INSIDE WALL OF REAR CASTING WITH MAIN BOARD REMOVED