




Photographs of EUT test position

Photo 1: Horizontal-Up  A photograph showing the underside of a white, curved object (likely a laptop lid) held in a horizontal position. A black mechanical fixture is visible below the object, supporting it. The background shows a laboratory setting with white walls and equipment.	Photo 2: Horizontal-Down  A photograph showing the underside of a white, curved object (likely a laptop lid) held in a horizontal position, viewed from a slightly different angle than Photo 1. A black mechanical fixture is visible below the object. The background shows a laboratory setting with white walls and equipment.
Photo 3: Vertical-Front  A photograph showing the underside of a white, curved object (likely a laptop lid) held in a vertical position. A black mechanical fixture is visible below the object. The background shows a laboratory setting with white walls and equipment.	Photo 4: Vertical-Back  A photograph showing the underside of a white, curved object (likely a laptop lid) held in a vertical position, viewed from the back. A black mechanical fixture is visible below the object. The background shows a laboratory setting with white walls and equipment.

EUT Constructional Details



.....The End of Test Report.....