



Client:	Xetawave LLC	Job Number:	JD99786
Model:	Xeta7	T-Log Number:	T99881
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 27	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions)




Client:	Xetawave LLC	Job Number:	JD99786
Model:	Xeta7	T-Log Number:	T99881
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 27	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (Radiated Emissions)




Client: Xetawave LLC	Job Number: JD99786
Model: Xeta7	T-Log Number: T99881
Contact: Sandee Malang	Project Manager: Christine Krebill
Standard: FCC Part 27	Project Coordinator: -
	Class: N/A

Test Configuration Photographs (Radiated Emissions)




Client: Xetawave LLC	Job Number: JD99786
Model: Xeta7	T-Log Number: T99881
Contact: Sandee Malang	Project Manager: Christine Krebill
Standard: FCC Part 27	Project Coordinator: -
	Class: N/A

Test Configuration Photographs (Radiated Emissions)



Client:	Xetawave LLC	Job Number:	JD99786
Model:	Xeta7	T-Log Number:	T99881
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 27	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurements)




Client: Xetawave LLC	Job Number: JD99786
Model: Xeta7	T-Log Number: T99881
Contact: Sandee Malang	Project Manager: Christine Krebill
Standard: FCC Part 27	Project Coordinator: -
	Class: N/A

Test Configuration Photographs (RF conducted measurements)




Client:	Xetawave LLC	Job Number:	JD99786
Model:	Xeta7	T-Log Number:	T99881
Contact:	Sandee Malang	Project Manager:	Christine Krebill
Standard:	FCC Part 27	Project Coordinator:	-
		Class:	N/A

Test Configuration Photographs (RF conducted measurements)



Client: Xetawave LLC	Job Number: JD99786
Model: Xeta7	T-Log Number: T99881
Contact: Sandee Malang	Project Manager: Christine Krebill
Standard: FCC Part 27	Project Coordinator: -
	Class: N/A

Test Configuration Photographs (RF conducted measurements)



Client: Xetawave LLC	Job Number: JD99786
Model: Xeta7	T-Log Number: T99881
Contact: Sandee Malang	Project Manager: Christine Krebill
Standard: FCC Part 27	Project Coordinator: -
	Class: N/A

Test Configuration Photographs (RF conducted measurements)

