

1. INTERNAL PHOTOGRAPHS


1.1 Disassembled sliding part



1.2 Phone after disassembling PWB and A-Cover



1.3 Disassembled Phone



1.4 D-Cover with GSM-Antenna, BT-Antenna and Speaker



1.5 Core PWB (without shieldings)

