





Ref report 16E086-3b part1

Appendix E

Spurious Emissions

Radiated








Fig E5 Scan 3GHz – 7GHz Vertical 3m




Fig E6 Scan 3GHz – 7GHz Horizontal 3m




Fig E7: Scan 7GHz – 11GHz Vertical 3m












Fig E8 Scan 7GHz – 11GHz Horizontal 3m













Appendix F

Band Edge Emissions

Radiated

Band 4







Ref report 16E086-3b part1

Appendix G

Peak to Average power Ratio

Conducted






Fig G3: QPSK 20MHz Mid channel 2135MHz

Note these are the worst case results

All results are < 11 dB

Limit is 13dB

Test result :-Pass

End of Report