







Test Setup Pictures


TEST REPORT #: EMC_SMAR1_037_11001_i201_3G_15.247

EIRP Test Setup Pictures

Band Edge Test Setup Pictures

Radiated Spurious Emissions Test Setup Pictures**30MHz – 1GHz****1-18GHz**

18-19.1MHz

Conducted Measurement Test Setup Picture

Conducted Emissions (AC Mains) Test Setup Pictures