



Photos

EMC and radio parameter test of Patient Resusci Simulator SimMan 3G

Performed for Laerdal Medical AS

Page 1 of 11

This exhibit is an extract of

DELTA Test Report A505816-3
DANAK-1910405
05 February 2009

containing only the photos of the test setups

DELTA

Venlighedsvej 4
2970 Hørsholm
Denmark

Tel. +45 72 19 40 00
Fax +45 72 19 40 01
www.delta.dk
VAT No. 12275110




Photo 4.2.1 Test setup regarding measurement of radio frequency voltage on mains.




Photo 4.2.2 Test setup regarding measurement of radio frequency voltage on mains.



Photo 4.3.1 Test setup regarding measurement of radio frequency electromagnetic field.



Photo 4.3.2 Test setup regarding measurement of radio frequency electromagnetic field.



Photo 4.4.1 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.4.2 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.5.1 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.5.2 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.6.1 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.7.1 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.8.1 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.8.2 Test setup regarding measurement of radio frequency electromagnetic field.




Photo 4.9.1 Test setup regarding measurement occupied bandwidth.



Photo 4.10.1 Test setup regarding measurement of radio frequency electromagnetic field.



Photo 4.11.1 Test setup regarding measurement of frequency tolerance.




Photo 4.11.2 Test setup regarding measurement of frequency tolerance.
Small loop antenna.