

Photos

**Test of Smart A-Cool Appliance Interface
according to FCC requirements**

Performed for Diehl AKO Stiftung & Co. KG

Page 1 of 5

This exhibit is an extract of

DELTA Test Report T202039
DANAK-19/12544
31 October 2012

containing only the photos of the test set-ups

DELTA
Venlighedsvej 4
2970 Hørsholm
Denmark

Tel. +45 72 19 40 00
Fax +45 72 19 40 01
www.delta.dk
VAT No. 12275110



Photo 4.1.1 Test setup regarding measurement of radio conducted limits, AC Mains.




Photo 4.1.2 Test setup regarding measurement of conducted limits, AC Mains.



Photo 4.2.1 Test setup regarding measurement of radiated limits below 1 GHz.




Photo 4.2.2 Test setup regarding measurement of radiated limits below 1 GHz.



Photo 4.3.1 Test setup regarding measurement of radiated limits above 1 GHz.



Photo 4.3.2 Test setup regarding measurement of radiated limits above 1 GHz.



Photo 4.8.1 Test setup regarding measurement of field strength of the fundamental.




Photo Error! No text of specified style in document..8.2 Test setup regarding measurement of field strength of the fundamental.