

This exhibit is an extract of DELTA Test Report F000001-03-2, DANAK ??????, containing only the photographs of the test set-ups.



Photo A2.1 AC mains conducted emission measurement



Photo A2.2 AC mains conducted emission measurement



Photo A2.3 AC mains conducted emission measurement




Photo A3.1 Radiated electromagnetic field measurement.



Photo A3.2 Radiated electromagnetic field measurement.



Photo A3.3 Radiated electromagnetic field measurement.