


Prüfbericht - Nr.:
Test Report No.

14002427 001

Seite 4 von 7
Page 4 of 7

Front side of internal view:




The yellow oval indicates the location of the antenna.

Prüfbericht - Nr.:
Test Report No.

14002427 001

Seite 5 von 7
Page 5 of 7

Front side of internal view (Zoom):




Prüfbericht - Nr.:
Test Report No.

14002427 001

Seite 6 von 7
Page 6 of 7

Rear side of internal view:



Prüfbericht - Nr.:
Test Report No.

14002427 001

Seite 7 von 7
Page 7 of 7

Side view of internal view:

